



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, December 1, 2020	Project Contact:	Brian Clauto
Spread I: Franklin	ST114650+00-14760+00 ATWS 372, 373	Weather:	Wet

	read I: Inklin			4650+00-14760+00 S 372, 373			Weather:		Wet				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	9		Clearing/Grubbing		Gra	ding		Trenching			Str	ringing/Welding
	Lowering/B	ackfilling		Final Grading		Ten	np. Stabilization		Perm. Stabiliza	ation	\boxtimes	Do	ormant
											Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
Areas of offsite sediment deposition observed?										\boxtimes			
 <u>Comments:</u> Inspected the following resources: S-H38, S-H37, S-H36, S-H35, S-H32, W-H11, S-H30, S-A18, S-A19/H26, S-A20, S-H28, S-A22 ECD's were in place and functioning at the designated crossings. 													
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - ST 14960+00 waterbar requires maintenance, bar does not meet height requirement. - ST 14720+20 waterbar requires maintenance, bar does not meet height requirement. - ST 14726+95 waterbar requires maintenance, bar does not meet height requirement. Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.													

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, December 1, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, December 1, 2020

Figure 1: ST14698 waterbar requires maintenance





Figure 3: ST14726+95 waterbar requires maintenance



Figure 4: Designated crossing S-H37, ECD's are in place.

